

Product Safety Recall



Hustler Turf Mowers

- Product:** Hustler Turf brand mower models:
Sport; FasTrak; FasTrak Super Duty; Hustler X-ONE; Super Z;
Hustler 1500
- Defect:** Certain fuel tanks were manufactured out of specification such that there is a risk that petrol may leak from the fuel tank near the vent fitting assembly.
- Hazard:** The possibility of leaking fuel is a potential fire hazard.
- What to do:** Stop using your mower immediately. Do not operate the mower until the vent fitting(s) has been replaced. Please contact your dealer to schedule an appointment to get a free vent fitting upgrade.
- Contact Details:** If you cannot contact your dealer, please contact Powerup Lawncare Products on 1300 363 027. Further information about the recall can also be accessed at www.hustlerturf.com.

See www.recalls.gov.au for
Australian Product Recall Information